

Playing field Update November 2023

- Brief visual inspection of playground no obvious deterioration aside from that previously referenced.
- Ongoing communication with Ardley FC regarding grass, trying to arrange a meeting with the Junior Chair.
- Have just received 2 quotes from Playdale for the playground, one is for upgraded equipment and one is for remedial work to address issues raised in ROSPA report. Two swings would need to be replaced as units but other issues raised can be addressed as individual items. Playdale were reluctant to remove existing structures as they didn't think they had reached end of life span and can be managed to extend life by repairs. Playdale will not condemn equipment and because they manufacture can always replace components.
- 'Jukebox structure' repairs, gate and labour ~ £3000 + VAT (doesn't include discount).
- Swings which due to rot were rated medium – replacement of structures with steel feet guards and adjustment of current seating arrangement (one to be replaced with a basket swing) ~ £5700 + VAT (no discount included).
- Quote provided to add to existing play area – Jungle climber, zip wire and a caterpillar swing.

B LANHAM 1/11/23